

Lick Creek - Winter 2007 Fieldwork
Findings and Recommendations

Table A-10: All Sites with Proposed Projects

Site ID	Name and Location	Project Type
CM-200	Wexford Woods Trail	Outreach & Education
ER-100 (OT-104)	Beta Rd Loop Apartments	Major Restoration
ER-110	RCH-113 below Lake Turbid at Brightleaf	Major Restoration
ER-111	RCH 112 at Brightwood Trail	Enforcement
ER-120, ER-150 (IB-120)	RCH 120 South of Ravenstone (near OT 122)	Major Restoration
ER-121	RCH 122	Volunteer
ER-170 (IB-170)	Kinard Rd at Phillips Farm	Volunteer
ER-401 (UT-401)	Power Easement west of Virgil Rd	Major Restoration
H-300a	McDonald's Restaurant at Route 70 and Mineral Springs Rd	Outreach & Education
H-300b	Undeveloped parcel South of McDonald's	Outreach & Education
H-301	Miracle Touch LLC adjacent to McDonald's on Route 70	Outreach & Education
H-302	MeElhoney Homes Route 70 east of Mineral Springs	Outreach & Education
H-303	Ward Trucking - Route 70	Outreach & Education
H-304	Jay Auto Sales - Route 70 at Hinesly	Outreach & Education
H-305a	Kawasaki - Route 70	Outreach & Education
H-306	Carolina Livery at Town and Country Homes on Route 70	Outreach & Education
H-307	Burger King at Route 70 and Mineral Springs Rd	Outreach & Education
IB-100	HWY 70 along RCH 101	Volunteer
IB-102	Along RCH103 North of HWY 70 at Amish Barn	Volunteer
IB-110	Wetland between Woodale and Alyea Ct in Brightleaf	Enforcement
IB-110	Wetland between Woodale and Alyea Ct in Brightleaf	Major Restoration
IB-120 (ER-120 and ER-150)	RCH 120 South of Ravenstone (near OT 122)	Major Restoration
IB-121	Along RCH-122	Volunteer
IB-160	RCH162	Enforcement
IB-170 (ER-170)	Kinard Rd at Phillips Farm	Volunteer
IB-201	Kingsmill Farm, Kemp Rd.	Volunteer
IB-210	Kingsmill Farm, off Kemp Rd	Enforcement
IB-211	Located off of Southview Rd.	Enforcement
IB-213	Wayward Dr.	Volunteer
IB-310	Parallel to Poplar in Brightwood Trails	Enforcement
IB-310	Parallel to Poplar in Brightwood Trails	Standards
IB-330	Homeowner off Kemp Rd	Volunteer
IB-331	Triple Crown Farm	Volunteer
IB-332	Triple Crown Farm	Volunteer
IB-333	Homes on 98 west of Kemp Rd	Volunteer
IB-334	Field on 98 west of Kemp Rd	Volunteer
IB-336	Off Baptist Road and Southview Rd	Volunteer
IB-350	Downstream of Olive Branch Rd	Major Restoration
IB-502, 503, 504, 506, 508	Falls Village Golf Course	Major Restoration
IB-507	Falls Village Golf Course	Major Restoration
MI-100	POWERLINE ROWS	Major Restoration
MI-110	RCH-110	Diabase Sill
MI-120	Control structure at large pond at Ravenstone	Outreach & Education
MI-121	RCH-121	Diabase Sill
MI-160	RCH-160	Diabase Sill
MI-161	RCH-162 - cave	Diabase Sill
MI-162	RCH-162	Diabase Sill
MI-163	RCH-162	Diabase Sill
MI-164	RCH-163	Diabase Sill
MI-165	RCH-163	Diabase Sill
MI-200	Located off Kintail Drive near Ennis Ct.	Repair
MI-201	Gravel operation, off Virgil Rd.	Enforcement
MI-205	Kingsmill Farm, off Kemp Rd	Enforcement
MI-208	Dirt Farm, off Coley Rd.	Enforcement
MI-301 (OT-301)	Brightleaf Detention Pond, near Pickard Place	Enforcement
MI-302		Diabase Sill
MI-303	Brightleaf - Golden Belt and Creighton Hall	Standards

Lick Creek - Winter 2007 Fieldwork
Findings and Recommendations

Table A-10: All Sites with Proposed Projects

Site ID	Name and Location	Project Type
MI-303	Brightleaf - Golden Belt and Creighton Hall	Volunteer
MI-304		Diabase Sill
MI-306	Inlet between Pizza Hut and Burger King	Repair
MI-307	Brightwood Trails - off Buckwood Ct	Enforcement
MI-308, 309, 310	Parallel to Poplar in Brightwood Trails	Enforcement
MI-311	Sewer Pump Station in Brightwood Trails	Enforcement
MI-313	Inlet in 70 ROW at McElhoney Homes	Repair
MI-320	North State Storage	Repair
MI-350	Olive Branch Rd Homeowner	Outreach & Education
MI-510	Power Easement north of Old Creedmor Rd	Outreach & Education
MI-511	River Dance Dr and Parker Falls Dr	Enforcement
MI-512	Mossy Ridge Ct Lot 15	Enforcement
OT-100	Fox Ridge Apartments	Major Restoration
OT-100 (upstream)	Fox Ridge Apartments	Outreach & Education
OT-104 (ER-100)	Beta Rd Loop Apartments	Major Restoration
OT-110	Sediment Basin at McCool Ct in Brightleaf	Enforcement
OT-111	Pond at Prospect in Brightleaf	Enforcement
OT-112	Sediment pond at Alyea Ct.	Enforcement
OT-113	Sediment Basin east of Eagle Lodge Rd in Brightleaf	Enforcement
OT-114	Sediment pond at intersection of Prospect and Morehead Hill Ct in Brightleaf subdivision	Enforcement
OT-116	Outfall from large pond at end of Ravenstone Ln	Enforcement
OT-120	Outfall into Lake Turbid Brightleaf Trakc 5 Phase II	Enforcement
OT-120 (downstream)	Lake Turbid in Brightleaf subdivision	Enforcement
OT-121	Eagle Lodge Rd near SC 120	Repair
OT-122	Large rip rap double 4 ft outfall from large pond at Rondelay in Ravenstone subdivision	Repair
OT-124	Ashburn Rd crossing	Repair
OT-125 and OT-126	Hillview Dr. crossing at SC-125	Repair
OT-127	In backyard of home on Woodtrelis Ct	Enforcement
OT-128	Between Grandimere Ct and Ravenstone Ct	Enforcement
OT-129, OT-130, OT-131, OT-132, OT-136, OT-137, OT-134, OT-135	RCH-122 Between Olive Branch and Hester Rd	Enforcement
OT-133	RCH-122 Between Olive Branch and Hester Rd	Enforcement
OT-139	211 Olive Branch Rd (front yard)	Enforcement
OT-154	RCH 151 between Bookman and Rondelay	Enforcement
OT-155, OT-156 (SC-152)	RCH 151 between Bookman and Rondelay	Enforcement
OT-301 (MI-301)	Brightleaf Detention Pond, near Pickard Place	Enforcement
R-300	Pizza Hut-Burger King at Route 70 and Mineral Springs Rd	Major Restoration
R-301	Route 70 Outfall adjacent to Budget Truck Rental	Major Restoration
R-302	Triangle Point Apartments on Angier Rd	Major Restoration
R-303	Amish Barns - business on Route 70	Volunteer
RCH 105	Between HWY 70 and powerline ROW/Leesville Rd	Enforcement
RCH 105	Between Leesville Rd and HWY 70	Outreach & Education
RCH 105	Between Leesville Rd and HWY 70	Volunteer
RCH-100		Diabase Sill
RCH-101		Diabase Sill
RCH-121		Protection
RCH-122, RCH-151, RCH-152	Neighborhood between Olive Branch Rd, Bookman, Rondelay	Outreach & Education
RCH-202	Located off Uppercross Ct.	Protection
RCH-203	Located off Uppercross Ct.	Protection
RCH-204	Located off Uppercross Ct.	Protection
RCH-205	Located off Uppercross Ct.	Protection
RCH-205		Diabase Sill
RCH-206	Located off Uppercross Ct.	Protection
RCH-207	Located off Kintail Dr.	Protection

Lick Creek - Winter 2007 Fieldwork
Findings and Recommendations

Table A-10: All Sites with Proposed Projects

Site ID	Name and Location	Project Type
RCH-208	Located off Kintail Dr.	Protection
RCH-209	Located off Kintail Dr.	Protection
RCH-210		Diabase Sill
RCH-213	Located off Carpenter Pond Rd.	Protection
RCH-214	Located off Coley Rd.	Protection
RCH-215	Along powerlines off Virgil Rd.	Protection
RCH-216	Along powerlines off Virgil Rd.	Protection
RCH-217	Along powerlines off Virgil Rd.	Protection
RCH-217		Diabase Sill
RCH-218	Along powerlines off Virgil Rd.	Protection
RCH-218		Diabase Sill
RCH-304	Downstream of Route 70 - Mineral Springs intersection; Parallel to future Pattersons Mill Rd	Protection
RCH-309	Parallel to Gilman	Protection
RCH-310	Mainstem near Brightwood Trails, parallel to Poplar	Protection
RCH-331	Tributary Upstream of Kemp Rd, near Triple Crown Farm	Protection
RCH-501	West of Copperleaf	Enforcement
RCH-501	West of Copperleaf	Protection
RCH-502	West of Copperleaf	Protection
RCH-506	West of Chestnut Hill Rd	Protection
RCH-507	Downstream of Ridgeline Dr	Protection
RCH-512	Silver Mist Ct and River Dance Dr	Protection
RCH-513	River Dance Dr and Wood Henge Dr	Protection
RCH-514	River Dance Dr and Mossy Ridge Ct	Protection
SC-103	Outfall from Amish Barns Stream adjacent to Route 70	Repair
SC-105	Hwy 70, northwest of Amish Barns	Repair
SC-107	HWY 70, btwn SC 105 and SC106 near guardrail	Repair
SC-111	North Durham Parkway Rd in Brightleaf subdivision	Enforcement
SC-112	On new road extension near Alyea Ct in Brightleaf subdivision	Enforcement
SC-120	Prospect Rd before Brightleaf Circle	Enforcement
SC-125	Hillview Dr. crossing	Enforcement
SC-126	Eastern Hillview Dr. crossing	Enforcement
SC-127	Olive Branch	Repair
SC-152 (OT-155, OT-156)	RCH 151 between Bookman and Rondelay	Enforcement
SC-170	Kinard Rd. crossing at Phillips Farm	Repair
SC-201	Kintail Drive.	Enforcement
SC-201	Kintail Dr.	Outreach & Education
SC-205	Ennis Ct.	Enforcement
SC-209	Junk yard located off Old Kemp Rd.	Enforcement
SC-301	Golden Belt Parkway	Standards
TR-100, TR-120, TR, 160	various locations	Volunteer
TR-101	At SC-106	Volunteer
TR-200	Uppercross Ct.	Outreach & Education
TR-200	Upper Cross Ct.	Volunteer
TR-210	Kingsmill Farm	Volunteer
TR-211	Wentz Rd.	Dumping in the stream
TR-211	Wentz Rd.	Volunteer
UT-110	RCH 110	Repair
UT-110	RCH 110	Volunteer
UT-111	Brightleaf subdivision near Alyea Ct	Enforcement
UT-301 & 302	Brightleaf	Standards
UT-303	Brightleaf	Standards
UT-401 (ER-401)	Power Easement west of Virgil Rd	Major Restoration